## **STEPPER MOTOR PROGRAM:**


```
#include <LPC17xx.H>
void delay(unsigned int x);
main()
LPC_SC->PCONP \models (1 << 15); /* enable power to GPIO & IOCON */
      LPC_GPIO0->FIODIR = 0x00078000;
                                               /* Configure P0.15,P0.16,P0.17,P0.18 as
Outputs*/
      LPC_GPIO2->FIODIR &= \sim(1<<10); /* Configure P2.10 as Input */
 while(1)
             LPC\_GPIOO->FIODIR = 0x00088000;
                                                     /* Write data for clock wise
direction*/
             delay(50000);
             LPC_GPIOO -> FIODIR = 0x00044000;
                                                     /* Write data for clock wise
direction*/
             delay(50000);
             LPC_GPIO0->FIODIR= 0x00022000;
                                                     /* Write data for clock wise
direction*/
             delay(50000);
             LPC\_GPIOO->FIODIR = 0x00011000;
                                                     /* Write data for clock wise
direction*/
             delay(50000);
 }
void delay(unsigned int x)
                                                                    /* Delay Routine */
for(;x>0;x--);
```

## **STEPPER MOTOR INTERFACE:**

General Purpose Input/Outp	ut 0 (GPIO 0) - Fast Interface	×
GPI00	31 Bits 24 23 Bits 16 15 Bits 8 7 Bits	0
FIO0MASK: 0x00000000		-
FIO0SET: 0x00000000		
FIO0CLR: 0x00000000		
FIOOPIN: 0x7FFF8FFF		V
Pins: 0x7FFF8FFF		7

	General Purpose Input/Output	ut 0 (GPIO 0) - Fast Interface	×
	GPI00	24 Pr 24 22 Pr 46 45 Pr 0 7	D: 0
?	FIO0DIR: 0x00078000	31 Bits 24 23 Bits 16 15 Bits 8 7	Bits 0
	FIO0MASK: 0x00000000		
	FIO0SET: 0x00000000		
	FIO0CLR: 0x00000000		
	FIOOPIN: 0x7FF80FFF		
	Pins: 0x7FF80FFF		

## STEPPER MOTOR IMPLEMENTATION:



## **STEPPER MOTOR IMPLEMENTATION:**

