

MRPL INSPECTION SUMMARY - CDU-2

Equipment: Pump P-201

Date: 10-Sep-2026

Status: seal replaced, returned to service

Next review: 72 hours

HANDWRITTEN FIELD NOTE

Observed: minor oil seepage near NDE bearing

Action: tightened gland, wiped area

Vibration re-checked: 2.8 mm/s - OK

Recommend: monitor daily for 3 days

Signed: R. Kamath 12-Sep-2026