Project: **DM2080** Current Revision: R1M1E1 **DM2080** Revision History: Reason for Change Date 5th July 2022 Revision **Changes Implemented** 21th October 2022 R1M1E1 Light bleeding of the LED light into the USB-C connector. Not enough feedback from buttons. - moved LED to the other side of the PCB - moved LED pins to CONNECTOR A to the PWM capable pins - added 100k resistors to gates of mosfes - resized the PCB board - added new buttons Luxonis Holding 1925 Harmony Park Drive Westminster, CO 80234 Title DM2080 Cannot open file C:\Users\BrianLuxonis\

















