Project: BC2087 Current Revision: R1M1E1

BC2087 Revision History:

Date	Revision	Reason for Change	Changes Implemented
22/Aug/2022	Iniital Release -> R0M0E0		
17/01/2023	ROMOEO -> R1MOE1	Change the right camera to be connected to DC3 not I2C0 as is at the moment. —Changed BRO INT and WAKE pins to IO42 and IO15 (MX) so that they are not no bone pins on KB. —PERST should be connected to IO. —Right camera should have a seperate reset line —Boot resistor for KB in wrong configuration —Expose UART for KB debugging. —No space for THI UART pins —FSYNC should be PWM capable	-Mored right camera to DCS -Changed pins to DO3 and DO3 (MX) -Changed PCIE_PREST to DO39 (MX) -Added right camera reset line to IO43 (MX) -Depupulated R45 -Depupulated R45 -Changed to SMD pins -Changed to SMD pins -Connected FSYNC to IO46 (MX) and IO14 (KB)

Title BC208	7		Luxonis Holding 1925 Harmony Park Drive	Cannot open file C:\Users\BrianLuxonis\
Size: Tabloid	Number: D2088000	Revision:R1M1E1		
Date: 14/02/202	3 Time: 16:57:57	Sheet 1 of 12	United States	14-11-11-11-11-11-11-11-11-11-11-11-11-1

1 2 3 4 5 6



























