GOLDEN BEAR EQUIPMENT INC.

CODE OF SAFE PRACTICES

Golden Bear Equipment Inc. | Chapter 4 of the Health and Safety Manual, issued as a standalone posting | v1.2, Effective October 1, 2026 | Revised October 15, 2026

This Code is posted at each job location and reviewed at orientation and in regular safety meetings. It states minimum requirements; the Health and Safety Manual and the pre-task plan govern the details of each task.

GENERAL SAFE PRACTICES

1. All work is performed under this Code, the Health and Safety Manual, and the pre-task plan (JHA) for the task. The plan names the heaviest or most repetitive manual handling, the aid or method to be used, and who rotates. When the work changes, the plan changes first.

2. Every employee has the authority and the duty to stop any work they believe is unsafe. No employee will be disciplined for a good-faith stop or report.

3. Report every injury, near miss, and instance of property, equipment, or utility damage to your supervisor before the end of the shift.

4. Report to work fit for duty: free of impairment from alcohol, drugs, medications that impair, and fatigue. Disclose impairing medications before the shift.

5. Required PPE is worn in all designated areas: hard hat, safety glasses, high-visibility apparel, safety-toe boots, and gloves suited to the task, plus task-specific PPE per the plan.

6. Horseplay, fighting, and pranks are prohibited on all work premises.

7. Keep work areas clean as the work proceeds: walkways clear, cords and hoses out of paths, nails removed or bent, materials stacked stable, spills cleaned or guarded immediately.

8. Inspect tools and equipment before use. Defective tools and equipment are tagged out of service and turned in, never used carefully.

9. Machine guards and safety devices stay in place and functional. Removing or defeating a guard is a serious violation.

10. Cord-connected tools operate on GFCI protection. Damaged cords are removed from service; grounding pins are never removed.

11. Ladders are inspected before use, set on firm level footing, and climbed with three points of contact facing the ladder. Consider a lift or scaffold before choosing a ladder.

12. Use mechanical means or a lifting aid first: forklift, dolly, cart, hoist, or the aid named in the plan. One person lifts no more than 50 pounds alone under good conditions; 50 to 100 pounds is a team lift or mechanical; over 100 pounds is mechanical, always. Keep loads close and turn with the feet, not the back. Rotate high-repetition and high-vibration tasks where the work allows. Report aches, pain, numbness, tingling, or loss of grip to your supervisor the same day; reporting is never disciplined.

13. Never dry-cut, dry-grind, or dry-sweep concrete, masonry, or asphalt. Use water or vacuum dust controls, always.

14. Wear hearing protection in posted areas and around high-noise equipment.

15. Follow the heat illness prevention program: drink water throughout the shift, use shade, take cool-down rests when needed, and watch coworkers for symptoms.

16. Know the emergency plan for your location: alarm, muster point, and who calls 911. Never move a seriously injured person except to prevent further injury, and never drive yourself for treatment of a serious injury.

17. Seatbelts are worn in every vehicle and every machine so equipped. Handheld phone use while operating is prohibited. A spotter is required whenever backing or offloading where any person could be in the path or vision is limited. Working alone, a documented walk-around immediately before the move is the accepted alternative.

18. Only trained and authorized employees operate equipment, machinery, or vehicles, or perform work requiring certification.

SHOP OPERATIONS

19. Apply lockout/tagout with your personal lock, release stored energy, block against movement, and verify zero energy before repair work.

20. Use rated lift points, locked lift arms, and jack stands. No one works under equipment supported by hydraulics alone.

21. Grinding and cutting require a face shield over safety glasses and functional guards.

22. Handle fluids per the SDS; know the eyewash location; contain and clean spills immediately.

FORKLIFT OPERATIONS

23. Only certified operators, on the specific truck type, with the seatbelt on for every movement.

24. In a tip-over, stay in the seat, brace, and lean away from the fall.

25. Travel with forks low and loads within rated capacity; travel in reverse when the load blocks forward view.

26. Sound the horn at corners and doorways; no one stands or passes under raised forks; no riders.

HOT WORK AND COMPRESSED GAS

27. Hot work outside designated areas requires a permit, a 35-foot cleared radius, an extinguisher, and a fire watch during and 30 minutes after.

28. Cylinders are stored upright and secured with caps on; oxygen and fuel gases are separated by 20 feet or a rated barrier; cylinders move by cart, never by the cap.

29. Compressed air is never used to clean skin or clothing and is never directed at a person.

YARD OPERATIONS

30. High-visibility apparel is worn wherever mobile equipment operates; make eye contact before crossing equipment lanes.

31. Equipment leaves the yard inspected, with the checklist signed by the person who performed it.

Stop work authority applies to every rule above. Questions, hazards, and anonymous reports: Corporate Safety, Sergio Robles, 626-366-2912.