Total:	Printed	Pages	:	4
--------	---------	--------------	---	---

Dall No	
NULL INO.	

E-1136

B. E. 3rd Semester (Main & Re) Examination – December, 2019

MACHINE DRAWING

Branch: (ME)


Code: BME-304

Time : Three Hours]	[Maximum Marks : 60
Notes Allege 11 Control of A (Tillian	11 - 1-1 (MCO) form questions from
Note: Attempt all questions from Section – A (Filling	
Section – B (Short Answer Type Questions)	and two questions from Section – C
(Long/Descriptive Answer Type Questions).	
SECTION - A	[Marks : 1 × 10 = 10
Note: Attempt all questions.	
1. Threads are classified into v thread, Acme thre	ad, Knuckle thread, etc. on the basis
of	1
(a) Start of thread	
(b) hand of helix	
(c) Profile of the groove	
(d) Surface	
2. Vice used for carpentry work has thread.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
(a) square (b)	buttress
(c) acme (d)	square

P. T. O.

3.	A riv	ret consists of a cylindrical part called	• • • • • • • • • • • • • • • • • • • •	1
	(a)	head	(b)	shank
	(c)	cylinder	(d)	snap
4.	If the	e volume of the extra length is lesser t	han th	ne head, the joint may be 1
	(a)	loose	(b)	tight
	(c)	broken	(d)	failed
5.	5. For double riveted butt joint, number of rows of rivet is			
	(a)	two	(b)	three
	(c)	four	(d)	one
6. If one cover plate is used, thickness of cover plate is kept times that of the				late is kept times that of the main
plate.				
	(a)	0.75	(b)	1.25
	(c)	1.125	(d)	1.5
7.	In a	the body is sawn to produce a	prolo	nged shank.
	(a)	semi-tubular rivet		
	(b)	tubular rivet		
	(c)	split pin rivet		
	(d)	compression rivet		
8.		are not hatched but darkened like	e soli	ds.
	(a)	Very thin parts		
	(b)	Thin parts		
	(c)	Thick parts		
	(d)	Single parts		

9.	Drawing showing the position of each part with respect to each other is called. 1				
	(a)	assembly drawing			
	(b)	part drawing			
٠	(c)	machine drawing			
	(d)	Installation drawing			
10.	Wor	rking drawing is used by			
	(a)	product department			
	(b)	customer			
	(c)	marketing department			
	(d)	designer			
		SECTION - B	[Marks : $5 \times 4 = 20$)	
Not	e: A	attempt any four questions.		•	
1.	Desc	cribe a Gib ant cotter joint with a suitable sketch.	5	,	
2.	Drav	w the eye foundation bolt give $\Delta = 24$ mm.	5		
3.	Wha	at are the types of riveted joint.	5		
4.	What is sleeve and cotter joint? Also explain why cotter is provided with taper? 5				
5.	Give two application of Knuckle joint. Write the design procedure of knuckle joint. 5				
6.	Drav	w free hand sketch of cotter joint.	5		
		SECTION - C			
Not	e: A	ttempt any two questions.			
1.	Drav	w Assembly of plummerblock with top view and front view as	given in fig. 1.		
'n		(3)	P. T. O.		



2. Draw the three views of Hexagonal-Headed Bolt of 24 mm diameter and 100 mm long with a Hexagonal nut and a washer. $10 \times 1 = 10$

OR

What is computer aided design and drafting? and What is the best purpose of learning it? Which software is mostly used and how? Also write any five command to draw machine component.