1. Handle

This is usually made of PVC materials.

2. Element (or) filament

This is the important part of a Soldering Iron (Converts electrical energy into heat energy).

3. Body

It connects the filament and soldering bit.

4. Soldering bit:

The bits are made up of copper, because it is good conductor of heat. It is used to make and break the joints. There are three types of bits generally available. They are,

i. Pencil bit

ii. Oval bit

iii. Bent bit

The selection of the bit depends upon the place and heat requirement.

5. Mains cord

This wire can be used to supply the input voltage (230V AC) to the Soldering Iron.

12 volts DC soldering Iron

It is used for soldering in Mobile PCBs and LED TV mother boards.



Fig 1.2 Soldering iron (12V DC)

Activity 1 :

Construct some models using hookup wires, flexible wires in soldering methods

Activity 2 :

Soldering practice using leg strips, Group boards and General purpose board in soldering methods

EE_Practicals_English Version.indd 233 11/10/2020 12:17:42 PM