

Spur Gear

2. HELICAL GEARS

If the teeth elements are twisted or helical, they are known as helical gears . These gears may be used for connecting shafts that are at an angle in the same plane or in different planes. They are smooth acting because there will always be more than one tooth in contact. Depending upon helix , the helical gears are classified as right hand type or left hand type.



Helical Gear

3. BEVEL GEARS

The power is transmitted between two shafts which are at right angles through bevel gears. It is in the shape of a truncated cone having all the teeth elements on the conical surface.



Bevel Gears

4. RACK AND PINION GEARS

This type of gear is used to convert rotary motion into linear motion or vice versa. The rack gears are straight and flat and have no curvature. This type of gear is used in lathe and drilling machine.



Rack And Pinion Gear

5. WORM AND WORM GEARS

Worm and worm gear are used to transmit power between two perpendicular shafts. Worm may be single threaded or multi threaded. The worm gear resembles



Worm and Worm Gear

GM_Chp09.indd 118 14-02-2019 11:43:55