


Smart Work

- The hand tools should be used for the specific purpose for which they are intended. They should not be placed near machine tool when their usage is not necessary.
- Marking and measuring should not be done on rotating and moving parts.
- Hacksaw blades should not be given under tightening when fitted on hacksaw frames.
- The hand tools should not be placed on electrical equipment.
- Tools like file, try square and hacksaw frames should not be used as a hammer or a screw driver.
- Tools having cutting edges like files, and scrapes should not be grouped with other hand tool when storing.

1.9 SAFETY PRECAUTIONS REGARGING MACHINE TOOLS

- Proper packing pieces should be used while lifting or shifting machine tools.
- Operators should work on machines which they are familiar with. When they choose to work on unfamiliar machines, accident may take place.
- The amount of parameters like feed, cutting speed and depth of cut should be selected according to the strength and rigidity of the machine tools.
- Sharped tools should not be placed on machine tools.
- Sudden failures and defects in the machines should not be corrected or attended by the operator himself. Proper technicians should be called for repair works.
- The machines should be stopped immediately if any abnormal sound comes from them.
- Notice board plate showing the message "The Machine Out Of Order" should be placed near the machines which are breakdown or under repair.
- The operator should not change the speed (or) lubricates when the machine is still functioning.
- While erecting new machine tools their weight, efficiency and speed are assessed and foundation bolts of sufficient strength should be installed.
- The machine tools should be maintained properly. It should be monitored regularly for scheduled maintenance and periodical lubrication.

1.10 SAFETY PRECAUTIONS REGARDING OPERATORS

- Operator should not wear ties and bows while working
- Operator should not wear small towel or clothes around his neck or on shoulders
- Operators should not rest his body on the machines at any time, when working on them
- Operator should wear tight clothing, they should avoid wearing loose dresses
- While operations like grinding, welding and chiselling, the operator should wear safety goggles

BME_Chp01.indd 6 11/9/2020 12:14:37 PM