

Safety Material Uses

- The operator should wear gloves while handling hot and sharp articles
- Operators should wear only leather footwear
- The operator should prefer working on machines which are familiar to him
- The operator should not touch unsafe and un-insulated electrical wires
- The operator should resist himself from changing the speed, marking or lubricating on functioning machines
- Metal chips should not be cleaned with bare hands but with proper brushes
- The operator should seek the help of others while handling heavy and fragile materials
- Safety plates and equipment should be installed before the machine is set on for operations
- Strict code of discipline should be followed in the workshop. Running, playing and chatting with others are to be avoided in the workshop
- The operator should wear earplug, helmet and mask while performing the machining operations
- The operator should know about the "FIRST AID"

MUST HAVE IN THE WORK SHOP



Fire Extinguisher


DO YOU KNOW?

Father of First Aid



Dr. Matthew Shields is known as the "Father of First Aid" in the United States. He was born in Crawfordville, Georgia, on 2nd November 1862.

Founder of First Aid



Robert Wood Johnson I (February 20, 1845–February 7, 1910) was an American industrialist Inventor of First Aid box.

BME_Chp01.indd 7 11/9/2020 12:14:39 PM