GENERAL WORKSHOP SAFETY PRECAUTIONS

1. The layout of machines in the workshop should be suitably done considering proper lighting and ventilation.
2. First-aid box containing proper medicine and instruments should be kept always ready in a workshop.
3. Inflammable materials should be kept in safe places with proper precautions.
4. Round and Cylindrical objects , sharps articles and tools should not be found in pathways for it may cause injuries to the workers.
5. Oil and grease should not be found spilled inside the workshop.
6. Hot objects should be kept separately wherein message like "HOT", " DO NOT TOUCH" are displayed

SAFETY PRECAUTIONS REGARDING OPERATORS

1. Operators should wear tight clothings. They should avoid wearing loose dresses.
2. Operators should not wear ties and bows while working.
3. The dress code of the operator does not allow him to wear small towel or clothes around his neck or on shoulders .
4. Operators should wear only leather footwear.
5. While performing operations like grinding, welding and chiseling, the operator should wear safety goggles.
6. Metal chips should not be cleaned with bare hands but with proper brushes.
7. Safety plates and equipments should be installed before the machine is set on for operation.
8. Operators should wear gloves while handling hot and sharp articles.
9. The Operators should resist himself from changing the speed , marking or lubricating on functioning machines.
10. Then Operators should seek the help of others while handling heavy and fragile materials.
11. Strict code of discipline should be followed in the workshop . Running, playing and chatting with others are to be avoided in the workshop.
12. The Operators should not rest his body on the machines at any time , when working on them.
13. The Operators should prefer working on machines which are familiar to him.
14. The Operators should not touch unsafe and un-installed electrical wires.