



Universal Surface Gauge

Uses of Surface Gauges

1. To find centres of round rods and square rods.
2. To set work pieces aligned to the axis of the lathe while held by chucks.
3. Can be used as a vernier height gauge to draw horizontal lines on work pieces.
4. To check parallelism of opposite sides on machined parts.
5. The scriber of the surface gauges is replaced by a dial indicator and used for alignment of machines tools.

2.13 V BLOCK

'V' block has a 'V' shaped groove and rectangle grooves on it. The angle of the 'V' groove is either 90° to 120°. The face of the 'V' block is square or rectangular in section. It is used to hold cylindrical work pieces when these work pieces are be machined in a drilling machine, shaping machine and milling machine. It is also used to hold round rods when some markings are to be done on it.



2D and 3D V-Block

The usual sizes of a 'V' block are 50mm to 250mm in length and 50mm to 100mm in width and height.

2.14 ANGLE PLATE



It resembles the English alphabet 'L'. It has got two sides absolutely perpendicular to each other. Usually it is made of cast iron. The sides of the angle plate have got slots and holes on it. It is used to hold work pieces on machine tools like lathe,

BME_Chp02.indd 27 11/9/2020 12:17:29 PM