
3. Burrs are removed by turning the tap back and forth.
4. High pressure should not be applied on the tap.
5. Proper wrenches should be used to operate the taps
6. Cooling agents should be used while tapping

2.16 DIES

Dies are used to cut threads on a round bar of metal, such as threads on bolt. It is a round or square block of hardened steel with a hole containing threads and flutes which form cutting edges.



2D and 2D Die Types and Uses

There are mainly two types of dies in common use. They are,

1. Solid Die
2. Adjustable Die

SOLID DIE

A solid die is one which has fixed dimensions and cannot be adjusted for larger or smaller diameter. Adjustable means that it can be set to cut on larger or smaller diameter.

ADJUSTABLE DIE

A circular adjustable split die shown in fig is very common. The die is split through one side and a slight adjustment is made by means of the set-screw. This screw is tightened up the die is opened up slightly, whilst unscrewing will cause the die to spring in. Another common type is the two-piece rectangular die in this type the dies are fitted into a special stock and they are closed by means of the adjusting screw. The size of the die is specified by the outer diameter of the thread to be made. The tools for holding and turning the threading die are called a die stock.

Importance Points to be Observed while Die

1. To ensure whether the job is cylindrical shape and the job should not be bigger than die.
2. The front face of the job should be chamfered.
3. To ensure the proper angle of the thread was formed.
4. When you are using the adjustable die, check whether both dies are of same dimensions.
5. Do not apply more pressure on the die.
6. Cooling agents should be used while die.

BME_Chp02.indd 29 11/9/2020 12:17:29 PM