Activities

1. Visit any one of the blacksmith workshop and submit the report. What are the various processes done there?

Questions

SJ7PYB

1 Mark

PART A

I. choose the correct option:

1. Which one is added to the surface of the steel, while nitriding
   a) Carbon and Nitrogen
   b) Nitrogen
   c) Carbon
   d) Hydrogen

2. The purpose of tempering is
   a) to improve corrosion resistance.
   b) to increase the hardness of the metal.
   c) to decrease the brittleness.
   d) to improve machinability.

3. The furnace with three Zone is
   a) Gas fired Furnace
   b) Salt bath Furnace
   c) Sintering Furnace
   d) Oil fired Furnace

4. _____ is a method of case hardening.
   a) Tempering
   b) Annealing
   c) Cyaniding
   d) Hardening

5. The temperature used for pack carburising is at
   a) 925°C
   b) 750°C to 850°C
   c) 30° to 50° above the higher critical temperature
   d) 500°C to 600°C

3 Marks

PART B

II. Answer the following questions in one or two sentences:

6. Define "Heat treatment"?
7. What are the methods of heat treatment?
8. What is lower critical temperature and upper critical temperature?
9. What is "Annealing"?
10. What are the types of furnaces?

GM_Chp05.indd 71 14-02-2019 11:39:03