9. Stationary armature and rotating field type is used in
   i) small size generators
   ii) For low voltages
   iii) Large size generators
   iv) For high voltages
   (a) (i) and (ii)
   (b) (ii) and (iii)
   (c) (iii) and (iv)
   (d) (iv) and (i)

10. A motor which is running in its synchronous speed is called as
   a) Synchronous motor
   b) Induction motor
   c) Three phase motors
   d) Single phase motors

11. The rotor used in three phase induction motor is
   a) Squirrel cage rotor
   b) Salient – pole type rotor
   c) Non- salient pole type rotor
   d) None of the above

12. Advantage of three phase Induction motors are
   a) Very simple in construction
   b) It's cost is low
   c) Very reliable
   d) All of the above

13. Slip is designed as
   (a) Ns –N
   (b) $\frac{Ns-N}{Ns}$
   (c) $\frac{Ns-N}{N}$
   (d) $\frac{N-Ns}{N}$

14. Squirrel cage induction motors are used in
   a) Lathes
   b) Drilling machines
   c) Fans
   d) All of the above

15. Slip ring induction motors are used in
   a) Lifts
   b) Hoists
   c) Compressors
   d) All of the above

16. One horse power is equal to
   a) 736 watts b) 756 watts
   c) 746 watts d) 766 watts

17. In India, frequency is
   a) 25 Hz b) 50 Hz
   c) 60 Hz d) 40 Hz

18. Which one is in correct?
   a) Single phase motors are not self starting
   b) Single phase motors are self starting
   c) Three phase motors are not self starting
   d) None of the above

19. Normally, which motor is used in Electric Mixie?
   a) Split phase motors
   b) Shaded pole motors
   c) Capacitor start motors
   d) Universal motors

20. Which motor is used in both A.C. and D.C supply?
   a) Split phase motor
   b) Shaded pole motor
   c) Universal motor
   d) Capacitor start motor

EMA_English_Chp08.indd 137 11/9/2020 3:24:22 PM