






NOTE:

- All dimensions should be noted in mm.
- Only one method of dimensioning should be used in a drawing.
- If the dimension value is less than 1, a zero is placed before the decimal point, example **0.5** and not **.5**
- Decimal point in a dimension should be written in line with the bottom line of the dimension value, example **0.5** and not **0 ˙5**
- Abbreviation for millimetres is not 'mms' but 'mm' only.

1.2.6 Principles of Dimensioning

S1. No	DIMENSIONING RULE	INCORRECT	CORRECT
1	Place the dimensions outside the views.		
2	Location of holes should be dimensioned in top views.		

Civil_English_Unit_1.indd 19 12/21/2019 1:06:39 PM