

iv) Zoom Center




before Zoom center




after Zoom center, magnification increased

v) Zoom All




2.2.6 Dimension




This command is used to dimensioning an object. If an object is drawn without measurements, then the drawing will not attain its fulfillment. If we furnish the details such as length, breadth, depth, angle, radius, diameter of the object, then the object gets nature of producing formation.

2.2.6.1 Methods of Dimensioning


In the classification of dimensioning there are linear, angular, radius, diameter and co-ordinates are available. Some of the dimension variable used in dimensioning is shown in the figure below.



For best results use the Aligned Dimension style for Isometric Dims.



Oblique Dimension Button



Civil_English_Unit_2.indd 45 12/21/2019 1:58:22 PM