
In this part we can decide the size of paper and orientation for plotting or tracing. The sizes of paper are A_4, A_3, A_2, A_1, A_0. The orientation for drawing may be landscape or portrait.


2.2.9 Isometric Drawings:




Object drawn by isometric drawing will be in visualizing shape. Full details of object with various view/angle is shown in orthographic projection. We can give full details only when an object is drawn both in orthographic and isometric views.

2.2.9.1 Isometric Projections


Isometric view means equal sized view. That is we can see the views of the 3 axis of an object in 120°.



The drawing should be drawn to full fize in this method. We should not use hidden line to show the inner part which are not visible.



The drawing should be drawn using 3 axes in this method.



ACTIVITY 6

Draw isometric views of a square and a rectangle by using AutoCAD and take print out.

Axis drawn in horizontal position at 30˚ is called right horizontal axis and the axis drawn at 30˚ to the left side horizontal position is called left horizontal axis. In between these axes, an axis at 90˚ is called vertical axis.

We have to change these three axes when we draw isometric drawing. That is, the cursor is moved to right axis and lines

Civil_English_Unit_2.indd 50 12/21/2019 1:58:23 PM