
Lean manufacturing

Lean manufacturing or lean production, often simply "lean", is a systematic method for waste minimization within a manufacturing system without sacrificing productivity.

Lean also takes into account waste created through overburden and waste created through unevenness in workloads. Working from the perspective of the client who consumes a product or service, "value" is any action or process that a customer would be willing to pay for.

Lean manufacturing makes obvious what adds value, by reducing everything else (which is not adding value).

This management philosophy is derived mostly from the Toyota Production System (TPS) and identified as "lean" only in the 1990s.



10.4. TROUBLE SHOOTING

10.4.1 Cooling System

Oil Heating	
Causes	**Remedy**
1. Cooling water may be Insufficient	Water to be filled in the radiator
2. Thermostat may not working	To be replaced
3. Water pump may not working	To be repaired or replaced
4. Valve timing may not proper	Set proper timing
5. Blocks may be there in Radiator	To be cleaned
6. Fan belt may cut	To be replaced
7. Excess carbon may deposited	To be removed
8. Blocks in the muffler	To be removed
9. Exhaust pipe may be bend	To be replaced

AM_Unit_10.indd 208 31-01-2019 18:04:27