


Fig 1. Cylinder block - Line Diagram

Reasons for Decarbonising

1. Black smoke exits through silencer.
2. Pre Ignition
3. More exhaust noise
4. Back firing
5. Due to depreciated piston ring the lubrication oil get burned and settled on the combustion chamber

AM_English_Practicals.indd 245 12/20/2019 5:50:01 PM