14. Don't allow an ill operator to operate the machine.
15. Exit path should be clearly marked and the pathway should be kept clear of any obstacles.
16. All the safety rules and procedures should be meticulously followed by all the employees.



Figure 1.1 Safety Equipments

1.2 SELF-SAFETY

An operator should prepare himself to do the work correctly, effectively within the stipulated time. This preparation will prevent the operator from accidents and such safety measure is called as self-safety. Figure 1.1 shows self-safety items and Figures 1.2 and 1.2(a) show their practice. The following are self-safety rules and should be followed.

1. Always wear fit clothes.
2. Don't have long hair.
3. Always wear shoe.
4. Operate a machine tool after getting proper training.
5. Sharp tools should be kept only at the designated place.
6. Handle sharp tools with proper safety wear.
7. Operate the machine/vehicle after pre – checkup.
8. Don't wear watches, rings during work.
9. Wear a helmet while travelling on a two-wheeler. Wear a seat belt while travelling in the car.



Figure 1.2 Self-Safety in Work Place

AM_Unit_01.indd 3 12/20/2019 4:19:07 PM