13. Most commonly used index number is:

(a) Volume index number

(b) Value index number

(c) Price index number

(d) Simple index number

14. Consumer price index are obtained by:

(a) Paasche's formula

(b) Fisher's ideal formula

(c) Marshall Edgeworth formula

(d) Family budget method formula

15. Which of the following Index number satisfy the time reversal test?

(a)Laspeyre's Index number

(b) Paasche's Index number

(c) Fisher Index number

(d) All of them.

16. While computing a weighted index, the current period quantities are used in the:

(a) Laspeyre's method

(b) Paasche's method

(c) Marshall Edgeworth method

(d) Fisher's ideal method

17. The quantities that can be numerically measured can be plotted on a

(a) p - chart (b) c – chart

(c) x bar chart (d) np – chart

18. How many causes of variation will affect the quality of a product?

(a) 4 (b) 3 (c) 2 (d) 1

19. Variations due to natural disorder is known as

(a) random cause

(b) non-random cause

(c) human cause

(d) all of them

20. The assignable causes can occur due to

(a) poor raw materials

(b) unskilled labour

(c) faulty machines

(d) all of them

21. A typical control charts consists of

(a) CL, UCL (b) CL, LCL

(c) CL, LCL, UCL (d) UCL, LCL

22. $\overline{X}$ chart is a

(a) attribute control chart

(b) variable control chart

(c) neither Attribute nor variable control chart

(d) both Attribute and variable control chart

23. R is calculated using

(a) $x_{max} - x_{min}$ (b) $x_{min} - x_{max}$

(c) $\bar{x}_{max} - \bar{x}_{min}$ (d) $\bar{\bar{x}}_{max} - \bar{\bar{x}}_{min}$

24. The upper control limit for $\overline{X}$ chart is given by

(a) $\overline{X} + A_2\overline{R}$ (b) $\bar{\bar{X}} + A_2 R$

(c) $\bar{\bar{X}} + A_2\overline{R}$ (d) $\bar{\bar{X}} + A_2\bar{\bar{R}}$

25. The LCL for R chart is given by

(a) $D_2\overline{R}$ (b) $D_2\bar{\bar{R}}$

(c) $D_3\bar{\bar{R}}$ (d) $D_3\overline{R}$

XII Std - Business Maths & Stat EM Chapter 9.indd 230 2/28/2020 5:11:36 PM