PART-D

Answer the questions in two page **(10 Marks)**

1. Draw the double layer simplex lap winding diagram for a DC machine having 2 poles, 6 slots and 6 commutator segments. Also mention the brush positions.
2. Draw the simplex wave winding diagram for a DC machine having 2 poles, 6 slots and 6 commutator segments. Also indicate the position of brushes.
3. Develop the winding table for a single layer lap winding of a 4 poles, 24 slots, AC three phase induction motor.



Reference Book

1. A text book of 'Electrical Technology' Volume-III B.L.Theraja and A.K.Theraja, S.Chand & Company Ltd.



Reference Internet Source

1. http://www.wikipedia.org
2. https://www.electrical4u.com

BEE_ENG_Chapter_09.indd 152 12/27/2019 10:36:02 AM