Practical

10

Dismantling, testing and assembling of A.C. 3 phase squirrel cage induction motor

AIM


To dismantle the given AC Three phase 400/440 V squirrel cage induction motor by using proper tools and to measure the insulation resistance by using megger and also check the condition of bearing and apply the quality grease in correct quantity for the bearing. Assemble and run the motor.

Tools and materials required

Sl.No.	Equipment's and materials	Nos.
1.	3 Phase A.C 400/440 V squirrel cage induction motor	1
2.	Bearing puller	1
3.	Insulated cutting plier	1
4.	Screw driver	1
5.	Cutter	1
6.	Scissor	1
7.	Nylon hammer	1
8.	Megger	1
9.	Knife	1
10.	Test lamp	1
11.	Grease	1
12	Feeler gauge	1

Procedure

Remove the shaft key screw by holding the pulley as shown below.



BEE_ENG_Pratical.indd 201 12/27/2019 10:54:36 AM