
at the torch and the tip of the welding torch is ignited to produce the flame. Because of the heat generated by the flame, the edges of the metal parts are melted. Filler rod provides the additional metal required for making the joint. The flux coated on the electrodes prevents oxidation and removes impurities. This method is suitable in welding metal parts of thickness varying from 2mm to 50mm. The temperature of the flame is around 3200^{0}C.



Gas Welding


Gas Welding equipments

The following equipments are necessary for gas welding

1. Gas cylinders
2. Regulators
3. Pressure gauges
4. Rubber hoses
5. Welding torch
6. Safety goggles
7. Gloves
8. Spark lighter
9. Wire brush

Gas cylinders

Oxygen and acetylene gases are stored in separate cylinders and used for gas welding. The colour of oxygen cylinder is black and the acetylene gas is stored in maroon cylinders. Oxygen is stored at a pressure of 125kg/cm^2. Acetylene gas is stored at a pressure of 16Kg/cm^2. In the cylinder.





Gas Cylinder

XII BME_English version CHAPTER 07.indd 132 1/8/2020 1:40:25 PM