
Brazing

In brazing, filler metal in molten state is filled between the metal parts of the joint. The filler rod is heated up to 450^0 C. The parts to be joined are cleaned and the molten filler metal is applied between the parts to make the joint. In this method, the metal parts are not melted.



Brazing


7.19 Types of welding joints

Following are the various types of welded joints

1. Butt joint
2. Lap joint
3. T-joint
4. Corner joint
5. Flange joint

Butt joint

Butt joint is a joint in which the corners or the edges of two metal parts are joined. The process is done by keeping the metal parts on a same plane. The edges of metal parts of thickness upto 5mm may be kept open square. If the thickness of the metal parts exceeds 5mm, edges of the parts need to be prepared in proper shape before welding.




Type of welding Joints

Lap Joint

It is a joint in which the metal plates are placed over lapping before welding. The edge of one part is welded with the surface of the other plate. There are two types of lap joint namely (i) single lap joint and (ii) double lap joint.

T-Joint

This joint is made by keeping the metal plates at perpendicular (90^0) to each other. Sheets with thickners over 3mm only are welded by this type of joints.



XII BME_English version CHAPTER 07.indd 138 1/8/2020 1:40:27 PM