

The method of setting the work in a four jaw chuck with the help of a surface gauge



A cylindrical work is held in a three jaw chuck



A rod of square section is held in four jaw chuck

Cutting speed

Speed can be defined as the distance an object moves in a particular time. In a lathe, the cutting speed is the distance travelled by a point on the outer surface of the work in one minute. It is expressed in meters per minute.

$$\text{Cutting speed} = \frac{\pi DN}{1000} \text{ m/min.}$$

Where,

'd' – is the diameter of the work in mm.

'n' – is the r.p.m. of the work.

π = 22/7 (or) 3.14

XII BME_English version_Practicals.indd 183 1/8/2020 1:50:16 PM