

Method of mounting the cutting tool on the tool post




Correct method



The cutting edge of the cutting tool is positioned exactly aligned to the axis of the lathe spindle.

Incorrect method-1



If the cutting edge of the cutting tool is positioned above the axis of the lathe spindle, the front clearance surface of the tool drags on the work. The cutting edge loses its cutting capacity due to wear.

XII BME_English version_Practicals.indd 185 1/8/2020 1:50:16 PM