

Incorrect method-2



If the cutting edge of the cutting tool is positioned above the axis of the lathe spindle, the cutting edge loses its keenness. When the tool is provided with depth of cut, the work rides over the tool. The cutting edge may be broken and the work surface is damaged.

Types of toolposts

Single screw toolpost



XII BME_English version_Practicals.indd 186 1/8/2020 1:50:16 PM