

Facing

Aim

- To machine a flat surface on the face of the given round rod (Facing)

Required instruments

1. Facing tool
2. Chucky key
3. Tool holder
4. Steel rule
5. Vernier Caliper
6. Surface gauge

Tool setting

A facing tool is mounted on the toolpost and its cutting edge is set exactly aligned to the axis of the lathe spindle. The compound rest is set at 0^0 mark.

Holding of the work

1. The metal piece to be machined is held in the chuck of the lathe.
2. Surface gauge is used to check whether the work is held aligning with the lathe axis.

XII BME_English version_Practicals.indd 188 1/8/2020 1:50:17 PM