

Exercise – 1



Operation – 1



Selection of cutting speed

Cutting speed = $\frac{\pi DN}{1000}$ m/min.

The above formula is used to arrive at a proper cutting speed for machining and the spindle speed is adjusted suitably.

Procedure

The lathe is switched on and the facing tool mounted on the toolpost is given feed by the cross-slide perpendicular to the lathe axis. A flat surface on the face of the work is generated.

Result

The finished piece of work is sent for inspection after the machining is over.

XII BME_English version_Practicals.indd 189 1/8/2020 1:50:17 PM