

Exercise – 2



Operation – 1



Marking

Marking is done on the work at the required point to indicate the length to be plain turned.

Procedure

1. The cross-slide is adjusted for required depth of cut and the lathe is switched on. The plain turning tool mounted on the toolpost is given feed by the carriage parallel to the lathe axis.
2. The above process is repeated until the required diameter is obtained. This is done by gradually moving the cross-slide after each cut.
3. During the process, the diameter of the work is checked with the help of outside caliper.
4. Finishing tool is used to obtain accurate dimensions of length and diameter.

Result

The finished piece of work is sent for inspection after the machining is over.

XII BME_English version_Practicals.indd 191 1/8/2020 1:50:17 PM