

Exercise – 4




Operation – 1



Facing operation

The lathe is switched on and the facing tool mounted on the toolpost is given feed by the cross-slide perpendicular to the lathe axis. A flat surface of the face of the work is generated.



XII BME_English version_Practicals.indd 195 1/8/2020 1:50:18 PM