

Exercise – 6



Operation – 1



Marking

Marking is done on the work at the required points to indicate the length of the portion to be knurled.

Procedure

1. The cross-slide is adjusted for required depth of cut and the lathe is switched on. The plain turning tool mounted on the toolpost is given feed by the carriage parallel to the lathe axis.
2. The above process is repeated until the required diameter is obtained. This is done by the gradually moving the cross-slide after each cut.
3. During this process, the diameter of the work is checked with the help of outside caliper and inside caliper.
4. Finishing tool is used to obtain accurate dimensions of length and diameter.
5. A knurling tool holder has one or two knurling rolls fitted to it. It is fitted on the toolpost and pressed against the work rotating at a slower speed. The feed is given by the carriage parallel to the lathe axis.
6. The knurling tool holder is relieved from the work after the operation is performed for the required length.

Result

The finished piece of work is sent for inspection after the machining is over.

XII BME_English version_Practicals.indd 200 1/8/2020 1:50:18 PM