Marking

Marking is done on the work at the required points to indicate the location of the groove after plain turning is performed to the required diameter.

Procedure

1. The cross-slide is adjusted for required depth of cut and the lathe is switched on. The plain turning tool mounted on the toolpost is given feed by the carriage parallel to the lathe axis.
2. The above process is repeated until the required diameter is obtained. This is done by the gradually moving the cross-slide after each cut.
3. During this process, the diameter of the work is checked with the help of outside caliper and inside caliper.
4. Finishing tool is used to obtain accurate dimensions of length and diameter.
5. The parting tool is brought to the marked location of the groove. The depth of cut is set by the cross-slide and the feed is provided by moving the carriage slowly between the marked points.
6. The above process is repeated until the required depth and the length of the groove is obtained.

Result

The finished piece of work is sent for inspection after the machining is over.

XII BME_English version_Practicals.indd 203 1/8/2020 1:50:19 PM