


Screwed mandrel

Centres



Centres are useful in holding the work in a lathe between centres. The shank of a centre has morse taper on it and the face is conical in shape. There are two types of centres namely


1. Live centre
2. Dead centre

Live centre




The live centre is fitted on the headstock spindle and rotates with the work.

Dead centre



Holding a work between Live and Dead centres



Holding a work between Live and Dead centres

XII BME_English version CHAPTER 01.indd 20 1/8/2020 1:45:55 PM