Advantages

1. Taper turning can be done to full length of the workpiece.
2. Taper thread cutting can also be cut in this method.


Diadvantages


1. This type of taper turning can be done up to angle of 8^0.
2. Internal taper turning cannot be done by this method.

1.20 Thread Cutting

Thread cutting is one of the most important operations performed in a lathe. The process of thread cutting is to produce a helical groove on a cylindrical surface by feeding the tool longitudinally.

1. The job is revolved between centres or by a chuck. The longitudinal feed should be equal to the pitch of the thread to be cut per revolution of the work piece.





Thread Cutting

XII BME_English version CHAPTER 01.indd 28 1/8/2020 1:45:58 PM