
Types of clamps

1. Plain
2. Slot clamp
3. Goose – neck clamp
4. Finger clamp

The following figure shows how to hold the work piece by means of T-slots, clamp and step-block.



T-bolt and clamp


Step block

It has long steps formation. It is used to hold the work firmly while using the T-bolt and clamps the step block supports the other end of the clamp. Work pieces of different sizes are held by levelling the clamp on different steps of the step block.

V-block

V-block is used for holding cylindrical work pieces. The work may be supported on two (or) three V-blocks according to the length of the work. The work is held on the V-groove and is clamped by straps and bolts. They are made of cast iron (or) steel and are accurately machined.


The following figure shows the use of a V-blocks.



V-block

Angle plate

The angle plates have two faces at right Angle to each other and made of cast iron. All the sides of a angle plate are machined accurately. Slots and holes are provided on both the faces of the angle plate. Work is clamped on one of its faces by means of bolts and nuts. The use of angle plate is shown in figure.



Angle Plate

XII BME_English version CHAPTER 02.indd 43 1/8/2020 1:44:53 PM