

spindle, the drill along with the sleeve is removed with the help of a drift. The drill is then removed from the sleeve by the same method.



Sleeve

Socket

When the tapered tool shank is larger than the spindle taper, drill sockets are used to hold the tool.




Socket

Drill sockets are much longer in size than the drill sleeves. A socket consists of a solid shanks attached to the end of a cylindrical body. The taper shank of the socket confirms to the taper of the drill spindle and fits into it. The body of the socket has a tapered hole larger than the drill spindle taper into which the taper shank of any tool may be fitted. The tang of the socket fits into slot of the spindle and the tang of the tool fits slot of the socket.

Drill chuck

This type of chuck is particularly adapted for holding smaller size of drills having straight shanks. The drill chuck has a taper shank at top portion of the chuck, which fits into the taper hole of the spindle. Bevel teeth are cut round the sleeve body which locates at the centre portion of the chuck. At the bottom of the chuck, there are three jaws are fitted at 120^0 each other. It is used to hold the drill bit.

The jaws are made of spring steel.



Drill Chuck

There are two types of chucks

1. Quick change chuck
2. Three jaw self-centering chuck

Special Attachment

Tapping attachment

The tapping attachment is used to hold the tool known as tap. It serves as a flexible connection between the spindle and the tap. The taper shank of the attachment

XII BME_English version CHAPTER 02.indd 49 1/8/2020 1:44:54 PM