


supported on the table by any one of the following methods.


1. Shaper vise
2. Clamps and stop pins
3. T-bolts and step blocks
4. Angle Plate
5. V-Block
6. Special fixtures

Vise

Vise is the most common and simple work holding device used in a shaper. Different types of vises are used in a shaping machine according to the need and they are: 1. Plain Vise, 2. Swivel Vise, 3. Universal Vise


Clamps and stop pins

T-bolts are fitted into the T-slots of the table. The work is placed on the table. The work is supported by a rectangular



Vise

strip at one end and by a stop pin at the other side. The screw is tightened to secure the work properly on the machine table. The use of stop pin is shown in Figure.



Clamp and Stop pin

T-bolts and step blocks

The step blocks are used in combination with T-bolts and clamps to hold the work directly on the machine table. The t-bolts are fitted in the T-slots of the machine table. One side of the clamp holds the work and the other side

XII BME_English version CHAPTER 03.indd 67 1/8/2020 1:43:58 PM