6.4.9 UCS Icon

You can see an L-shaped line in the lower-left corner of the drawing area. It is called the UCS icon; UCS is short for "User Coordinate System."

- The UCS icon is useful primarily for drawing in three dimensions.
- The icon is not needed for 2D drafting, and you can turn it off with the UCSICON command. Type the command name, and then enter the Off option, as follows:
- Command: ucsicon (Press ENTER.)
- Enter an option [ON/OFF/All/Noorigin/ORigin/Properties] <ON>: off (Press ENTER.)




Fig. 6.34. UCS Icon

6.4.10 Navigation Bar

The Navigation Bar is displayed in the drawing area and contains navigation tools.




Fig. 35. Navigation Bar

6.4.11 Status Bar

The Status Bar which is located below the command line, and docked in the lower-right corner of the window is called Application Status Bar.

It contains so many buttons which help you to create a drawing very easily. You can easily turn ON or OFF these buttons just by clicking on them.

Some buttons are hidden by default. You can also display more buttons on the status bar by clicking the Customization button at the bottom right corner and selecting the options from the menu.

Tip. When in AutoCAD 2016, the bottom status bar is not displaying, Type in STATUSBAR on the command line, and hit enter. Change the value from 0 to 1. Now the Status Bar appears on the bottom of the window.

Command: STATUSBAR ↵
Enter new value for STATUSBAR <0>: 1 ↵

XII CompTech_English version CHAPTER 06.indd 181 10-04-2019 11:04:28