



Kejian	LG	LG	LG	LG	Motorola	Motorola	Nokia
K698	G5300	G5400	G5600	G7100	C650	E365	6100
Dualband	Dualband	Dualband	Dualband	Dualband	Triband	Dualband	Triband
84 x 44 x 21	106 x 44 x 22	86 x 46 x 22	105 x 43 x 19	89 x 46 x 24	103 x 44 x 20	107 x 45 x 20	102 x 44 x 13
91	85	85	90	99	92	93	76
Clamshell	Bar	Clamshell	Bar	Clamshell	Bar	Bar	Bar
externa	Internal	External	Internal	External	Internal	Internal	Internal
260 KB	65,536	65,536	65,536	65,536	65,536	65,536	4,096
128 x 160	128 x 128	128 x 160	128 x 160	128 x 160	128 x 128	128 x 160	128 x 128
4-Way	2-way	NA	NA	4-Way	2-way	5-way	4-way
500	NA	200	500	200	1000	300	300
SMS, EMS, MMS	SMS	SMS, EMS, MMS	SMS, EMS, MMS	SMS, EMS, MMS	SMS, EMS, MMS	SMS, MMS, EMS	SMS, EMS, MMS
32 MB	NA	1.3 MB	NA	1.3 MB	1.8 MB	2 MB	669 KB
Polyphonic	Polyphonic	NA	Polyphonic	32-Tones	Polyphonic	Polyphonic	Polyphonic
Li-Ion	Li-Ion	Li-Ion (760 mAh)	Li-Ion (760 mAh)	Li-Pol (780 mAh)	Li-Ion (800 mAh)	Li-Ion (700 mAh)	Li-Ion (720 mAh)
2	3	3	NA	2	6	3	4
120	200	230	NA	200	215	150	235
✓	✗	✗	✓	✓	✓	✓	✗
✓	✗	✗	NA	NA	NA	NA	✗
✓	✗	✗	NA	✗	✗	✗	✗
✗	✗	✗	NA	✗	✗	✗	✗
✗	✗	✗	NA	✗	✓	✗	✓
✗	✗	✗	NA	✗	✗	✗	✗
✗	✗	✗	NA	✗	✗	✗	✗
✓	✓	✓	✓	✓	✓	✓	✓
✓	✓	✓	NA	✓	✓	✓	✓
✓	✗	✓	NA	✓	✓	✓	✓
✗	✗	✗	NA	✓	✓	✗	✓
✗	✗	✗	NA	✓	✓	NA	✓
✓	✓	✓	NA	✓	iTAP	✓	T9
✓	✗	✓	NA	✓	✓	NA	✓
✗	✗	✓	NA	✓	✓	✗	✗
✓	✗	✓	✓	✓	✓	✓	✗
✓	✗	✗	NA	✗	✓	✗	✓
✓	✓	✓	✓	✓	✓	✓	✓
✗	✗	✓	✓	✓	✓	✓	✓
✗	✗	✗	NA	✗	✗	✗	✗
✓	✗	✗	✓	✗	✓	✗	✗
✓	✓	✓	NA	✓	✓	✓	✓
NA	✗	✗	NA	✗	✗	✗	✓
✗	✓	✓	✓	✓	✗	✗	✓
✓	✗	✗	✓	✗	✓	✗	✓
16,650	7,900	8,800	10,550	14,000	9,500	10,500	10,589
NA	www.lgezbuy.com				www.lgezbuy.com		

J2ME (Java 2 Micro Edition) A technology that allows programmers to use the Java and related tools to develop programs for wireless and mobile devices such as cellular phones and personal digital assistants (PDAs).

Lithium Ion (Li-Ion) A type of rechargeable battery for cell phones

generally lighter weight than earlier battery types, has a relatively longer cycle life, and generally does not suffer from “memory” effect.

Memory Effect A battery problem caused by repeated charging before a battery is fully drained. This results in deterioration and prevents batteries from accepting a full charge. It occurs most often in NiCd