



PS5 benchmark leak

The first PS5 benchmark leaks supposedly show huge performance gains over PS4. <https://dgit.in/july19-84>



BMW Electric Motorcycle

The Motorrad Vision DC Roadster concept electric motorcycle looks like it's from the future. <https://dgit.in/july19-85>




Expensive and difficult to repair

The primary problem of this laptop is that even if the smallest component wears out or stops working completely, you will probably end up replacing half of the machine, which is not inexpensive at all.



MacBook Pro 2019



Possible problems of the metal dome

The metal dome, when pressed down comes back up with a spring. There are multiple possibilities which could cause this switch to crack or wear out like manufacturing defects, fatigue, prolonged heat, moisture and corrosion. If the switch does crack, the key may behave erratically or may fail entirely.



Revised butterfly switch

The butterfly keyboard, which made its debut with the 2015 Retina MacBook, has had many issues including jamming of keys and extremely short throw (how far it goes down when pushed). The 2019 butterfly switch keeps the silicone membrane but changes the materials in the springy metal dome and even the plastic material that covers it.

Images courtesy:
 **IFIXIT**
 Website: iFixit.com
 Teardown link: <https://dgit.in/MacBookPro19>