

Please take a look at the configuration given below:

```
Building configuration...
Current configuration : 9165 bytes
!
! Last configuration change at 18:35:54 UTC Wed Dec 16 2015
version 15.1
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
!
hostname livedigital
!
boot-start-marker
boot system flash:c2800nm-adventerprisek9-mz.151-4.M3.bin
boot-end-marker
!
!
logging buffered 128000
enable secret 5 $1$dIX2$/3T6ABkfIVRTXubC6Ub60
!
no aaa new-model
!
!
network-clock-participate wic 0
network-clock-participate wic 2
!
!
dot11 syslog
ip source-route
!
!
ip cef
!
!
!
ip host vxml_content 192.168.3.180
!
!
isdn switch-type primary-ni
isdn voice-call-failure 0
!
!
!
trunk group 26
max-calls any 30
!
!
!
trunk group 20
max-calls any 30
preemption enable
preemption tone timer 4
!
!
!
application
service trydtmf http://192.168.3.180/voice/tryDtmf.vxml
!
!
```

```
mrccp client session history records 10
mrccp client rtpsetup enable
crypto pki token default removal timeout 0
!
!
!
!
license udi pid CISC02851 sn FHK1324F0G0
archive
log config
hidekeys
!
redundancy
!
!
!
controller E1 0/0/0
framing NO-CRC4
pri-group timeslots 1-31
trunk-group 26 timeslots 1-31
!
translation-rule 5
!
!
interface GigabitEthernet0/0
ip address 192.168.3.103 255.255.255.0
duplex auto
speed auto
!
!
interface Serial0/0/0:15
no ip address
encapsulation hdslc
dialer pool-member 2
isdn switch-type primary-ni
isdn integrate calltype all
no cdp enable
!
control-plane
!
!
!
voice-port 0/0/0:15
!
!
!
mgcp profile default
!
!
!
dial-peer voice 6681400 pots
service trydtmf
incoming called-number 668141
direct-inward-dial
port 0/0/0:15
forward-digits all
!
!
!
line con 0
```