




INTERIOR

The Mark IV's Daimler 105hp engine was positioned in the middle of the same compartment as the crew, creating a great deal of heat, fumes, and noise. The tank's lack of suspension and seating meant that the crew also had a rough ride—when not in action, the gunners would often ride on top or walk beside the tank.

11. Starboard side 6-pounder gun breech 12. 6-pounder ammunition stowage
 13. Machine gun ammunition stowage 14. Oil tank to lubricate secondary gears
 15. Secondary gear levers 16. Engine 17. Oil filler cover 18. Differential housing
 19. Front commander and driver's positions 20. Vision port lever 21. Steering lever 22. Front machine gun ball mount (without gun) 23. Brake pedal
 24. Clutch pedal 25. Differential lock lever