

Tech Meeting July 2026

Home Service Network

June Tech KPI

*High KPI List

Tech Name	Regio	NPS	HASS
Omar Dorville	NJB	100.0	100.0
Junhan Kim	NJB	100.0	100.0
Kwan Keun Lee	NJB	100.0	100.0
Il Heung Park	NJB	100.0	100.0
Rodney Montesino	NJB	100.0	93.8

*Low KPI List

Tech Name	Regio	NPS	HASS
Tae Yong Sung	NJB	16.7	42.9
Marcus Leslie	PAP	20.0	64.3
Sean Pacurucu Caminero	NYL	25.0	76.9
Richard Rampersaud	FLO	30.8	80.0
Chansoo Kim	MDB	33.3	84.6


Winning Branch for June is “NJB.” Congratulations!

- High KPI-listed technicians: Thank you for your performance!
- Low KPI-listed technicians: 3 months of low scores in a row would result in a warning letter.

****Please try to meet the target score of each KPI.****

NPS Notice

(NPS: Net Promoter Score)




Our NPS score continues to fall short of the target. Last month, we recorded an NPS of 74.8, which met our goal.

As the importance of NPS is constantly highlighted, we ask that everyone gives this their full attention.

June NPS: 74.8

NPS Target goal: 70

HASS Notice



The HASS usage trend is improving. Last month, the usage rate reached 82.1%. Please continue this progress and ensure we meet the 80% target.

If the following issues occur while using HASS:

1. App closes during report transmission
2. Pending report does not transmit after failure

Users must send error information via Configuration > Management > Send error information to the HASS admin.

The system will automatically attach the log to the administrator's account for email submission.

***Important:** The error log must be sent within 10 minutes of the issue. After 10 minutes, the log will be automatically deleted.

HASS usage at 75% or below will result in compensation exclusion.
Three consecutive months below the HASS goal may result in a warning letter.

June HASS: 82.1%

HASS Target goal: 80%

Temporary Update to No-Ticket Day Pay and Scheduling

Due to ongoing low-ticket volume, we will be temporarily pausing payment for no-ticket days, effective with the current pay period that began on 6/8/2026. We appreciate everyone's continued efforts and hope to resume normal operations once ticket volume increases.

If low ticket volume is anticipated, technicians will be notified by 3:00 P.M. the previous day if a no-ticket day is expected. Tickets may also be reassigned based on daily volume unless the assignment falls under a designated exception (Special Area, SSR, 2nd Man team, or Additional Case).

If tickets are assigned and serviced for the day, technicians will receive full workday pay, regardless of the number of hours worked.

Please note that new contracts have been or will be issued. This memo, while aligned with the updated contracts, supersedes any previous contracts or agreements, regardless of whether a technician chooses to sign.

**** Mandatory PCR IH Service Notice ****

- **For IH PCR: 43, 50, 55, 58, 60, 65**

All PCR services will be handled In-Home!

Samsung has issued a directive requiring that PCR service transition from pick-up to in-home service. While we have made efforts to delay this change, it can no longer be postponed. Accordingly, all technicians will be required (without exception) to perform PCR service in-home in the near future.

In the interim, while PCR service continues via pick-up, all technicians are expected to utilize the TVs brought into the office to practice and develop their PCR skills. This will help ensure a smooth and timely transition to in-home service.

Please be advised that in-home PCR service is not optional; it is a mandatory work requirement for all technicians.

PCR Service Notice



Primer handling guide :

<http://69.74.172.226:5000/sharing/05sNj8zlL>

Panel Component Repair :

<http://69.74.172.226:5000/sharing/wiIe6RN6s>

Open cell repair guide :

https://players.brightcove.net/1366266421001/dz7WPjL3O_default/index.html?videoId=6390735936112



Primer handling guide



Panel Component Repair



Open cell repair guide

Monthly STG Training

***** Updated training must be completed by the 20th of every month. Failure to complete the training will result in a warning letter !!!**

****ATTENTION****


If any of your technicians currently do not have access to STG's Ticket Management feature, please use the link below to let us know:

<https://www.surveymonkey.com/r/TECHVIEWSTG>


Accessing the Content on Cornerstone

In order to find the assigned courses, follow these simple steps:

1. Log into STG > ELEARNING
2. This should take you to the LMS Home Page
3. Learning → Go to View Your Transcript
4. Assigned Training (Video+ Quiz) will be shown if you have the appropriate RA's. After the video you will then be directed to the quiz portion.



STG Trainings could be uploaded at any time. Please keep an eye on the updated training, especially 2~3 days before the 20th, and complete all the required training.



Field Service Compliance Policy – 2026

This notice serves as a formal reminder to all Home Service Network technicians regarding mandatory field service documentation picture requirements.

* For every service ticket, the following four (4) required pictures must be attached without exception:

Required pictures:

- Photo of the unit and the surrounding area before service
- Photo of the unit and the surrounding area after service
- Signed Liability Waiver Form
- Clear photo of the Serial Number label

Please note that there are no exceptions for follow-up visits. Even if previous photos or documents already exist, technicians are still required to upload new before/after condition photos and a newly signed Liability Waiver Form for every service visit. Failure to comply with this policy, or any violations identified during the review process, will result in the issuance of an official warning letter.

****Please also be advised that if a technician receives three (3) or more official warning letters for any reason, HSN reserves the right to apply incentive deductions and adjust ticket volume accordingly immediately.****

****All tickets must be completed on-site** ■

With proper pictures and notes uploaded **

All Technicians – Please be mindful of the following:

1. All tickets must be updated and completed on-site.
2. Photos taken on-site must be uploaded immediately along with the update note.
- 3. Mandatory 4 pictures must be uploaded on the tickets**
***(Before service picture, After service picture, S/N label, HSN liability form)**
4. Make it a habit to complete tickets onsite — do not wait until the end of the day.

*If extra parts are needed for the service, Photos or needed parts must be sent through the chatroom

*** Tickets are required to be completed no later than 10 PM***

**** If tickets are not completed on time, we will be unable to process claims properly, which may result in payment delays.****



Guidelines for Issuing Formal Warning Letters

Please also be advised that the following may result in the issuance of an official warning letter:

- Low NPS scores for consecutive 3 months
- Low HASS completion percentage for consecutive 3 months
- Failure to complete monthly STG training on time
- No call / no show incidents
- Refusing assigned tickets
- Any other actions or conduct that may negatively impact the company (ETC.)
- No four required pictures for every ticket

Furthermore, if a technician receives three (3) or more official warning letters for any reason, HSN reserves the right to apply incentive deductions and adjust ticket volume accordingly. Technicians who continue to receive official warning letters may also be subject to termination.

****Please be advised that the Field Service Compliance Policy is effective immediately.****

MPU SAW

Reminder: Official Policy Reminder and Tips (Multiple Parts Usage Policy - HA)

We would like to remind you of the **Multiple Parts Usage Policy (MPU)**, and provide the additional parts combinations highlighted below. Please review and familiarize yourself with the process and guidelines as provided below.

- **What is MPU?**
Multiple Parts Usage Policy – References the use of multiple parts in the same repair; that Field Service Engineers have identified should **NOT** typically not be replaced during the same repair.
- **What if my technician truly believes that the parts combination is necessary for the repair they are completing?**
 1. If your technician believes that the part combination is required, please advise your technicians to **contact the Technical Support team at 800-849-2198 for approval prior to replacing the parts while on site at the unit's location.**
 2. For successful WER approval, the parts combination should be added to the ticket prior to contacting TCC. If parts are not on the ticket at the time of contacting TCC, it may result in delayed WER approval.
 3. If TCC approves the technician's request; an APPROVED WER will be added to your service ticket, **by the Tech Support Agent.**
 - a. If above steps were followed, the WER will be applied **within 1 hour.**
*If the WER is not applied to the ticket within 1 hour, you may contact Tech Support for an update
 - b. Please do not submit the WER directly
- **What if my technician does not call Tech Support from the customers location?**
Failure to follow the process above will result in the ticket to be pending and not being able to move forward unless one of the parts is removed from the ticket. After removing the extra part, you may complete the ticket and file the claim.
- **How do I know if the WER is approved?**


In GSPN, navigate to the Service Action Worksheet Menu → SAW Status. Here you can view the status of all of your SAWs and WERs.



You may also see the WER status in the SAW/WER tab directly in the service ticket:

No	SAW ID	Category	Status	Request Date	Requester	Request Amt	Confirm Date	Confirmer	Confirm Amt
1	4161111485_0001	Why En Exception	Approved	07-07-2025	John	0.00	07-07-2025	PSM10 ID	0.00

- **Will I get an error message to tell me the process was not completed properly?**
If these parts combinations are used on a claim without the Tech Support WER approval an error will populate (PC029) indicating that the “These parts cannot be claimed together. Please check if all parts are needed.”



ASSY S.TUB BACK & ASSY DRUM	Should not be changed in the same repair
ASSY BUTTON	More than 1 of this part should not be used in the same repair
ASSY COVER DOOR	More than 1 of this part should not be used in the same repair
ASSY DETERGENT	More than 1 of this part should not be used in the same repair
ASSY DRAWER	More than 1 of this part should not be used in the same repair
ASSY S.PANEL CONTROL	More than 1 of this part should not be used in the same repair
ASSY S.TUB BACK	More than 1 of this part should not be used in the same repair
ASSY DRUM	More than 1 of this part should not be used in the same repair

OTWEU SC4U Ticket

OTWEU OOW Exception for SC4U (CLPW) covers parts and labor, except for SSR

HSN

Service Report

NJ

2 days

CLPW

Confirmed

BFSCS12

05/11 10:00 ~ 11:00 AM @ BROOKLYN

RF32CG5100SRAA (SAMSUNG)

Details

Parts

Tracking

Chat

Billing

** OTWEU OOW Exception for SC4U ***

** MODLALERT DA81-05707AFILTER FROZEN DA97-13047A -> LEAK FROM BACK

Quick Action

General Information

Status	Engineer Assigned
Sub Status	Part Shipped

< Mobile version>



Ticket Detail Information (SS)

[Ticket](#) > [Ticket List](#) > [Ticket Detail Information \(SS\)](#)

*** OTWEU OOW Exception for SC4U ***

*** MODEL ALERT *** DA81-05707AFILTER FROZEN DA97-13047A -> LEAK FROM BACK

*** 2 related ticket(s) found ***

Ticket #

Refresh

Account
BF5C512

Why
CLPW

Product
Refrigerator

TAT
2d

Status
Confirmed

Solution
K

General Information
Service Tracking
Repair Parts
SAW
Compensation
Other Information
Billing

Customer Information

< Web site>

OTWEU OOW Exception for SC4U (CLPW) will cover Parts and Labor, except for SSR which over 5 years from DOM

SC4U (CLPW) refers to a Customer Pre-Paid Samsung Out-of-Warranty (OOW) fee. Please DO NOT offer any additional OOW charges to the customer if the ticket is under SC4U (CLPW).

OTWEQ

Memo - S90D OLED TV No Power Symptom

Please be advised that Field Service will begin making a warranty accommodation for **specific OLED units** with **No Power Symptoms** through the unit's 2nd year, only for the SMPS/Power board and labor. (Part numbers shown below)

This accommodation will ONLY cover the models/part noted below. If the repair requires any other parts, the repair should be charged to the customer.

Eligible Models/Part:

Model	Warranty covered part
QN77S95DAFXZA	BN44-01333A
QN77S95DDFXZA	BN44-01333A
QN77S90DAFXZA	BN44-01329A

Model	Warranty covered part
QN77S90DDFXZA	BN44-01329A
QN83S90DAEXZA	BN44-01371A
QN83S90DDEXZA	BN44-01371A

Eligible Required Symptoms:

Power TV cannot be powered on Technical

Warranty Status:

*Will show OTWEQ

OLED SCREEN,QN77S90DDFXZA UNIT LED TV TFT CTV In Home 28		Sales Country	
Prod Date 10/01/2024		Labor/Parts 12 12	
Wty Exception OTWEQ OLED 2nd year		Wty Term LP (L)12/31/2025 (P)12/31/2025	

Warranty Claim

Defect Code:

*Use defect code NPOW or DEAD (Sample)

Defect Code	SRG032 Power Problem	Repair Code	SRG000-Parts Replacement
	NPOW No Power(FC)	Recommend	59-REPLACED MAJOR COMPONENT PART

Part No:

*Only the corresponding SMPS /Power board should be included on the warranty claim. (Sample)

No	Location	Part No	Part Description
9301	12	BN44-01329A	DC VES POWER BOARD LTP040N_PVDACDC-ITE

Any customer that has questions regarding the warranty or status of their product should always be directed to 800-

Please be advised that OTWEQ tickets only cover power board (SMPS) replacement work. If no part is used and only diagnosis is performed, we cannot claim the ticket through Samsung. **For OTWEQ tickets, please either replace the power board (SMPS) or charge the customer the OOW trip/service fee.** Any issue unrelated to the power board (SMPS) must be treated as OOW.

Memo – Oven 2nd Year Accommodation – (Specified Electric Models)

Please be advised that Field Service will begin making a warranty accommodation for **specific Oven Models with a heating issue; for specified models, with the defect and parts detailed below.** Units that meet the criteria will have a 2nd year warranty accommodation only for the parts referenced below.

****If you are dispatched a ticket with this accommodation, the symptoms have already been confirmed and may be intermittent at the time of your visit. You must complete the repair; use the relevant parts mentioned and file your warranty claim with the correct defect codes shown below. ****

This accommodation will ONLY cover the models/part noted below. If the repair requires any other parts, the additional repair /parts should be charged to the customer.

When this warranty is applied to a service ticket, the Warranty Exception/Over 30 field will populate "Oven 2nd year wty" IF the required criteria below is met.

Warranty Term: LP

L/P+

Warranty Exception/Over 30: Oven 2nd year wty

Production Period: 2024 February to 2024 December

Models:				
NE63A6511SS/AA	NSE6DG8500SRAA	NSE6DB850012AA	NSE6DG8500MTAA	NE63D6711SR/AA
NE63A6751SS/AA	NE63A6751SG/AA	NE63A6111SS/AA	NSE6DG8550SRAA	NSE6DG8300MTAA
NSE6DG8100SRAA	NSE6DG8100MTAA	NE63T8111SS/AA	NE63D6511SR/AA	NSE6DB850212AA
NSE6DG8300SRAA	NSE6DB830012AA	NE63BG8315SSAA	NE63T8751SS/AA	NSE6DG8502MTAA
NE63A6711SS/AA	NE63A6311SS/AA	NSE6DB870012AA	NE63T8751SG/AA	NE63T8511SS/AA
NE63A6511SG/AA	NE63A6711SG/AA	NSE6DG8700SRAA	NSE6DG8502SRAA	NE63A8711QN/AA
NE63BB871112AA				

Parts: Parts that will be covered in the 2nd Year.

* If none of the parts above or additional parts are replaced, the customer is responsible for payment.
Any additional parts should be excluded from the claim as they will not be reimbursed.

Part Number:	Description:
DG44-01005C	REGULATOR ENERGY; PER001-11D,15A, D-Cut,Si
DG44-01006C	REGULATOR ENERGY; PER001-12D,15A, D-Cut,Du
DG44-01006D	REGULATOR ENERGY; PER001-02D,18A, D-Cut,Du
DG44-01007C	REGULATOR ENERGY; PER001-13D,15A, D-Cut,Tr
DG44-01012A	REGULATOR ENERGY; PER002-01D,6.0 A, D-Cut,S

Defect Codes: In order for the warranty extension to be applied to the claim, one of the below defect codes must be used:

Eligible Defect Codes:	
HC3 (Excessive heating)	FCP (UNIT OVERHEATING)
HH2 (Over cooking)	HBX (Other faulty indication)

Please be advised that **Oven 2nd Year Accommodation tickets only cover the listed regulator energy parts for the specified electric models.** If none of the covered parts are replaced, or if the repair requires any other parts, the customer is responsible for payment. For these tickets, please either replace the covered part if applicable, or charge the customer as OOW. Any issue unrelated to the covered regulator energy parts must be treated as OOW.

Memo – Laundry Combo 2nd Year Accommodation–(WD53DBA900HZA1)

Please be advised that Field Service will begin making a warranty accommodation for the Laundry AI Combo Model (WD53DBA900HZA1) **with a drying issue; with the defect and parts detailed below. Units** that meet the criteria will have a 2nd year warranty accommodation only the parts referenced below and the labor related to this repair.

****If you are dispatched a ticket with this accommodation, the symptoms have already been confirmed and may be intermittent at the time of your visit. You must complete the repair; use the relevant parts mentioned and file your warranty claim with the correct defect codes shown below. ****

This accommodation will ONLY cover the models/part noted below. If the repair requires any other parts, the additional repair /parts should be charged to the customer.

When this warranty is applied to a service ticket, the Warranty Exception/Over 30 field will populate “AI Combo 2nd year wty” IF the required criteria below is met.

Warranty Term:

LP

L/P+

Warranty Exception/Over 30:

AI Combo 2nd year

Production Period: 2024 January to 2025 February

Model: WD53DBA900HZA1

Parts: Parts that will be covered in the 2nd Year.
* If none of the parts above or additional parts are replaced, the customer is responsible for payment. Any additional parts should be excluded from the claim as they will not be reimbursed.

Part Number:	Description:
DC62-00981A	NOZZLE; WD8000DK, PP+TD30%, T2, NATURAL,
DC97-24231A	ASSY NOZZLE; WD8000DK

Defect Codes: In order for the warranty extension to be applied to the claim, one of the below defect codes must be used:

Eligible Defect Codes:	
HC1	No heating
HC2	Weak heating
HG5	No drying

Please be advised that **Laundry AI Combo 2nd Year Accommodation tickets only cover the listed nozzle parts for model WD53DBA900HZA1**. If no covered part is replaced, or if the repair requires any other parts, the customer is responsible for payment. For these tickets, please either replace the covered nozzle part if applicable, or charge the customer as OOW. Any issue unrelated to the covered drying/nozzle repair must be treated as OOW. Please be aware!

STG Process for Installation Issue

Reminder:

STG Process for Identifying Installation Related Issues -Update to required Process
As of 6/1 /23 - This has been a required process to avoid warranty payment rejections.

As announced in May 2023, capturing Installation Failures in STG is crucial to understanding where we can improve our installation process and satisfy our customers' needs better and is **now required**.

We have made this process to report an Installation Issue/Failure **even easier** for your techs. Please take a moment to share this information with your technicians as soon as possible.


IMPROVEMENTS:

1. The Installation Issue/Failure flag; has been moved to the main ticket screen in your techs ticket view in STG
2. Purchase date/production date of the model is no longer a factor. Any repair in which a cosmetic or function issue was caused by improper installation or delivery should be flagged using this process.

Make sure to proceed STG Process for Installation Issue!!

Simple steps:

1. "Installation Fault" button
2. "Installation Related Repair"
3. Proceed to follow the prompts
4. Add pictures
➤ Submit



Note: There is no approval needed or further action requested. This step is to simply notify Samsung of the installation issue

*If the ticket is not eligible based on production date a pop up will appear after selecting Installation Related Repair.

Smart Service

Samsung has released an updated STG BE version 2.92, which includes a new Diagnosis Code feature for Appliance tickets.

When available, the **Diagnosis Code** will provide additional information based on the customer unit’s usage pattern. This code may appear with or without regular error codes and can only be viewed through the Product Support button in STG.

Please make sure to check the Tech Icon on each ticket:

-  Red icon: Content and/or Diagnosis Code is available
-  Blue icon: No content/code is available
-  Green icon: Information has already been viewed

After reviewing the available content, technicians must select “**Acknowledge**” in the Contents menu.

Please review this update and make sure to follow the process when checking Appliance tickets in STG.

STG Update (BE) - Diagnosis Code

An updated STG version [v2.92] is available for STG BE users that includes a new additional feature on Smart Service Function to provide you with some critical information about the customer unit.

The STG BE Appliance tickets will begin to include the **Diagnosis Code** when available.


What is Diagnosis Code?

- Pre-cautious code that occurs based on customer usage pattern.
- This code is normally hidden and will **only be visible inside the Product Support Button** and cannot be seen in GSPN.
- This code may come with or without any other regular error codes

To access this information:

1. View your ticket in STG
 - If the Tech Icon is red a content and/or Diagnosis code is available
 - If the Tech Icon is blue: No content/ code is available
 - If the Tech Icon is green: You have viewed the information on the ticket (however you may go back to it if needed)
2. After viewing the content, **It is required to select Acknowledge** in the Contents menu.


Product support team is available to assist you with any trouble completing this update. Please contact CSDproductSupport@sea.samsung.com for support.



Smart Service

Count of Latest Ticket	Column Labels		
Row Labels	O	X	Grand Total
HOME SERVICE NETWORK, NC	3	5	8

→ Using rate is currently **38%**



Product Support recommendation!

Starting now, we are implementing a Smart Service system, When viewing the ticket list, **If you see a red stamp, it is very important that you click the ‘Contents’ button and check the details.**

Once the content has been reviewed, the red stamp will automatically change to green, indicating that confirmation is complete.

Please note that blue stamps do not require any action.

However, RED STAMP MUST BE CHECKED, and you must make sure they have changed to green after reviewing the content.

if you see a red stamp, Click the ‘Contents’ button and check the details

This screenshot shows a customer ticket for Kashif Paul. The ticket details include the name, phone number (240) 855-1514, address (7700 DOWN CT, LAUREL MD), and product information (DW80CG4051SR AA LP Warranty). There are buttons for 'TICKET UPDATE' and 'Customer Sign'. A red stamp icon (a person with a red 'X') is highlighted by a red box. Below the ticket, there are buttons for 'SMS', 'Chat', and 'Contents' (highlighted by a red box), along with a 'Content s' button.

This screenshot shows the same customer ticket for Kashif Paul. The 'Contents' button is highlighted by a red box, indicating that the user should click it to review the ticket details. Other buttons visible include 'Action Req', 'Parts', 'Photo Upload', and 'TCC Support Request'.

Once the contents are reviewed, the stamp will turn green

This screenshot shows the same customer ticket for Kashif Paul. The stamp icon has changed from red to green (a person with a green checkmark), indicating that the ticket has been reviewed. The 'Contents' button remains highlighted by a red box.

You don't need to do anything for the blue stamp

This screenshot shows a customer ticket for Kashif Paul with a blue stamp icon (a person with a blue checkmark) highlighted by a red box. The blue stamp indicates that no action is required for this ticket. A 'HASS' logo is also visible next to the stamp.

MPU SAW

Starting 7/25/2025, All HOME ELECTRONICS (HE) , HOME APPLIANCES (HA) products are subject to MPU SAW/WER.

This includes MONITOR and B2B Units as well.

If more than one part is required, please make sure to contact Technical Support (T/S) and proceed with the diagnosis together.

There is no separate T/S line for B2B units

Please continue using the existing T/S contact.

Refresh

BFSC577

IW

LED TV

15d

Claimed

KKL 07/18

Tracking

Repair Parts ²

SAW ²

Compensation

Other Information

Billing

Category	Status	Requestd
SRC41	Approved	07/15/2025
Warranty Exception Request	Approved	07/17/2025

HSN New Policy Update for unmount and mount unit

• Service Guidelines: Mounting & Safety

1. Preparation & Accessibility

- Service Area: The unit must be accessible and free of obstructions.
- Unmounting: If the unit is mounted and cannot be unmounted by the Tech or the Customer, document the issue, complete the ticket, and advise the customer to contact Samsung for a new request.
- Liability Waiver: A signed waiver is mandatory before any unmount/remount work.
 - If refused: Note the refusal, complete the ticket, and refer the customer to Samsung.

2. Safety Restrictions (Do Not Proceed)

Complete the ticket and advise the customer to contact Samsung if:

- Height Limit: The anchor point or center of the TV is higher than 8 feet from the floor.
- Obstructions: Any physical barriers prevent a safe unmount/remount.
- Lack of Assistance: The customer provides no help for unmounting when required.

3. Second-Man Documentation

If a second person is required, you must include:

- A clear statement that a second man was used.
- Full Name and Phone Number of the second person.

Updated Time Tracking Procedures

***Time Tracking Procedures**

- Start of Day:
 - Punch in via fingerprint upon arrival at the office to mark the start of the workday.
 - If reporting directly to a client (CX) home, punch in remotely via uAttend upon arrival.
- End of Day:
 - Punch out via uAttend when leaving last visited CX home.
 - If required to report back to the office at the end of the day, punch out via fingerprint or uAttend upon arrival back at the office.
- Real-Time Punching:
 - All punches (including remote punches) must be completed in real-time.
 - Late or missed punches should be reported to a supervisor immediately to ensure proper
 - correction.
- Verification & Records:
 - All remote punches must be completed via uAttend.
 - Geolocation will be used to verify punch records.
 - Final worked hours will be recorded in uAttend.
 - Employees can view

***Any issues related to unexpected arrivals, difficulty punching in or out, or missed punches must be reported promptly to Management or Human Resources. Timely reporting ensures proper documentation and resolution.**

Prepaid Payment Policy for Out-of-Warranty Services

Please be advised that the following policy regarding out-of-warranty service tickets is mandatory and not optional:

1. Full payment is required and must be received before any service or part replacement is performed.
2. If payment is refused or not received, service will not be provided under any circumstances.
3. For any repair involving part replacement, the full cost of the part must be paid in advance prior to proceeding with the repair.
4. This policy must be followed at all times and cannot be overridden by a technician's discretion or a customer's request.
5. No exceptions will be permitted unless formal prior approval is obtained from management.
6. For prepaid service tickets, the company has already collected the initial service fee from the customer; therefore, technicians may not refuse to visit the customer's home.

***** This policy is mandatory, effective immediately, and applies to all out-of-warranty service tickets. *****

How to Count and Manage NPS Score

(NPS: Net Promoter Score)

*NPS score count: Total Survey Rate score/Survey count = NPS score

Survey Rate score 10 to 9 = +100 pts

Survey Rate Score 8 to 7 = 0 pts

Survey Rate Score 6 to 1 = -100 pts

Please explain to the customer that the Samsung Survey is all about the **Technician** and has nothing to do with **the product** or the **Customer Service Representative (CSR)**.

If the customer is satisfied with the service but dislikes the other situation or other complaints, Please let the customer know that on Survey, there are writing comment section on the survey after giving out the Survey Rating Score between 9 and 10.



Importance of managing KPI



Samsung operates with a strong emphasis on KPI performance. In many instances, their approach may seem demanding or rigid; however, as a service provider under Samsung, we are obligated to comply with their operational guidelines and expectations.

Key performance indicators such as NPS (Net Promoter Score) and HASS are critical metrics that directly impact the volume of ticket assignments we receive. Unless we consistently meet these KPI targets, Samsung will not allocate additional tickets to us.

It is therefore imperative that all technicians make a concerted effort to improve and maintain strong KPI performance.