HONG SENG ASSEMBLY SDN BHD

NO.7137 JALAN SUNGAI PUYU, 13020 BUTTERWORTH, PENANG.

| Operator | ZUL |
|----------|----------------|
| Vehicle | energy : Disel |

| VEHICLE | Static vertical forces : 2875 daN | | | | |
|--|---|-------------|-------------|---------------|--|
| HV | Main | Emergency 1 | Emergency 2 | Parking Brake | |
| Axles Breaking force Efficiency Unbalance Dissymetry | 1+2 1749 daN 59 % (2) 9 % (2) 7 % | | | | |

| AXLE (1) | Left | | Axle | | Right | |
|------------------------------------|------|-----|--------------------|---------------|-------|-----|
| Side Slip vertical static force | 919 | daN | -2. 1887 | 7 m/km daN | 968 | daN |
| SERVICE BRAKE wheel locked | | | 16 | eft | | |
| Braking force | 582 | daN | 1175 | daN | 593 | daN |
| Efficiency Dissymetry | 63 | % | 62 3 | % % | 61 | % |
| Unbalance | | | 2 | % | | |

| AXLE (2) | Le | ft | Ax | le | Rig | ght |
|-------------------------------------|-----|-----|-----|-----|-----|-----|
| vertical static force SERVICE BRAKE | 488 | daN | 988 | daN | 500 | daN |
| wheel locked | | | 1 | eft | | |
| Braking force | 274 | daN | 574 | daN | 300 | daN |
| Efficiency | 56 | % | 58 | % | 60 | % |
| Dissymetry | | | 7 | % | | |
| Unbalance | | | 9 | % | | |

| OPACITY | | | |
|---------|----------------------------|-------------------------|--|
| | Absorption OPACITY K | 12.00 % 0.29 m-1 | |
| | Max engine speed | 0 rpm | |

| 000 GOOD | 000 ACCEPT. <u>000</u> E | BAD (0) Axle |
|----------|---------------------------------|--------------|
| | v 3.0.6.4 | PAGE 1/ |