
Testing Procedure-Lever

Connections:



Connections:

L- to pin 5

R- to pin 17 but with 1k ohm resistor as shown in figure

L+ and R+ remains open

+(positive) connected to 3.3V via 1k ohm resistor

-(negative) Connected to ground

Testing procedure:

- 1. Upload the code and please check the serial monitor, it will print either of below
 - Forward 1
 - Forward 2

- Reverse Based on the position of lever