

CNC Machines Projects

Submitted To :


Dr/ Mohamed Elkeran

&

Eng/ Ahmed Saeed



NAME	Hussein Ahmed Ibrahim Abdelaziz Rizk
LVL	300
Department	MTE
ID	803084842
No.	11



Report
Turning
(Section)

Report
Milling
(Section)

Report
Turning
(Lecture)

Report
Milling
(Lecture)

-
- Content
-



Report Turning (Section)

Part


Similar to

External Turning

Programming

Exercise 1

Page 131



- Code

```
O0002 (Turning Report)
N005 G21 G90 G18 G94 F100;
N010 T0101;
N015 G00 G54 X25.0 Z10.0;
N020 M04 S1000;
N025 M08;
N030 G00 Z-2.0;
N035 G01 X-1.0;
N040 Z1.0;
N045 G00 Z5.0;
N050 X20.0;
N055 G01 Z-32.0;
N060 X22.0;
N065 G00 X25.0 Z5.0;
N070 X15.0;
N075 G01 Z-17.0;
N080 X22.0;
N085 G00 X25.0 Z5.0;
N090 X10.0;
N095 G01 Z-7.0;
N100 X22.0;
N105 G00 X25.0 Z5.0;
N110 M05 M09;
N115 M30;
```


File(F)ViewDisplayMachine OperationWorkpieceMeasureExercise/TestWindow(V)Help

DOOSAN - FANUC i Series

PROGRAM00002N00000
00002 (FG:EDIT)
00002 (Turning Report) ;
;
N005 G21 G90 G18 G94 F100 ;
;
N010 T0101 ;
N015 G00 G54 X25.0 Z10.0 ;
N020 M04 S1000 ;
N025 M08 ;
N030 G00 Z-2.0 ;

MEM*****S0L100%
02:32:12
PRGRMCHECKCURRNTNEXT(OPRT)

OPNQGR7A8B9D
XCZYFL4T5W6SP
MI SK TJ 1, 2# 3=
UH WV EOB E - + 0. . /
POS PROG OPS/SET SHIFT CAN INPUT
SYTEM MSG CSTM/GR ALTER INSERT DELETE
PAGE PAGE
HELP
RESET

FANUC

NC ON NC OFF
MACHINE READY EMG.RELEASE ALARM M02/M30 CHUCKING TOOL MEASURE SINGLE BLOCK OPTION BLOCK SKIP OPTION STOP DRY RUN

RAPID OVERRIDE
FO 25% 100%
X1 X10 X100
INCIDENTAL FEED
X Z

FEEDRATE OVERRIDE
80 100 120 140 160 180 200

SPINDLE OVERRIDE
80 100 120 140 150

SPINDLE CONTROL MODE
FWD RVS JOG
START STOP

CHUCK MODE SELECT
PROGRAM PROTECT

DOOSAN

FEED HOLD CYCLE START

QUILL ADV /RET.

RS232C

Size(mm): Length 65.000 Radius 12.1 REL:X -375.000, Z -522.954 ABS:X 25.000, Z 5.000 T:1 22.Doosan FANUC0i(Lynx220L)

2:32 AM 8/29/2024




Report Milling (Section)

Part

Similar to

Contour Milling
Programming Exercise 2
Page 122



Code

O0001 (Milling Report)

N005 G21 G90 G95;

N010 M03 S1000;

N015 M08;

N020 M06;

N025 G00 X1.0 Y1.0;

N030 G01 Z-2.0 F20;

N035 G01 X99.0 F80;

N040 Y49.0;

N045 X1.0;


N050 Y1.0;

N055 G00 X-5.0 Y-5.0;


N060 Z6.0;

N065 M05 M09;

N070 M30;




SwanSoft Result




Report Turning (Lecture)

Part




Code

```
O0002 (Turning Task)
N005 G21 G90 G18 G94 F100;
N010 T0101;
N015 G00 G54 X25.0 Z10.0;
N020 M04 S1000;
N025 M08;
N030 G00 Z-2.0;
N035 G01 X-1.0;
N040 Z1.0;
N045 G00 Z5.0;
N050 X20.0;
N055 G01 Z-32.0;
N060 X22.0;
N065 G00 X25.0 Z5.0;
N070 X10.0;
N075 G01 Z-7.0;
N080 G03 X15.0 Z-11.33 R5.0;
N085 G01 Z-17.0;
N090 G03 X20 Z-19.0 R2.0;
N095 G01 Z-32.0;
N100 X23.0;
N105 G00 X25.0 Z5.0;
N110 M05 M09;
N115 M30;
```





SwanSoft Video

Report Milling (Lecture)




Part



Code

O0001 (Milling Task) N005 G90 G21 G17 G04; N010 G00 X19.40 Y11.57; N015 G43 H01 Z2.0; N020 M03 S1000; N025 M08;	(First Letter "H") N030 G01 Z-2.0 F20.0; N035 G01 Y42.21 F80.0; N040 Y26.89; N045 X29.86; N050 Y42.21; N055 Y11.57; N060 Z2.0; N065 G00 X38.87 Y11.61;	(Second Letter "A") N070 G01 Z-1.0 F20.0; N075 G01 X47.01 Y42.44 F80.0; N080 X54.93 Y11.61; N085 X50.97 Y27.0; N090 X42.94; N095 Z2.0; N100 G00 X65.21 Y12.44;	(Third Letter "I") N105 G01 Z-1.0 F20.0; N110 G01 X78.74 F80.0; N115 X72.04; N120 Y42.94; N125 X65.21; N130 X78.74; N135 Z2.0; N140 G00 Z40.0; N145 M05; N150 M30;
--	--	--	--



SwanSoft Video

Thank  You!