



SCHEME FOR MCC3B-SEAFORTH GRAIN

[illegible]

Contacts N/C 11R4 (TH4) —
302²¹ & 303²² Cables shorted out
322²³ & 323²⁴ Cables shorted out

REVISION 12	REVISION: 10
-------------	--------------

REVISION 12	REVISION: 10
Notes added as	LOW INTERLOCK TERMINALS

Notes added re-	LSN INTERLOCK TERMINALS CORRECTED. ALSO FEEDS TO
-----------------	---

Notes added re-
shorting out cables

shorting out cables TWP 4 & TWP 3 collected.

691 & 692. 693 & 694

691 & 692. 693 & 694
302 & 303 322 & 323

302 & 303. 322 & 323

3.12.76

2-12-76	12/3/78	A.L.J.B
---------	---------	---------

2/12/70	13/3/78	A.L.J.B
REVISION: 3	REVISION: 2	

REVISION: 3	REVISION: 2
-------------	-------------

323 WAS 324

ADDED.

ADDED:	
ORIGIN: E-0	ORIGIN: E-0

ORIGIN: EIS.	ORIGIN: EIS.
1/12/73: SCD	1/12/73: SCD

ORIGIN: EST.	ORIGIN: EST.
10/3/71 SGD. JT.	4/3/71 SGD JT.

10/3/11 SGD. J.A.	4/3/11 SGD. J.A.
-------------------	------------------

NOTE - 'IR' Relays are Turnhead position relays

SCHEME FOR MC
position relays

THE DESIGN AND MANUFACTURING INFORMATION CONTAINED IN THIS DRAWING IS THE EXCLUSIVE RIGHT OF DEWHURST & PARTNER LTD. AND MUST NOT BE COPIED OR USED FOR MANUFACTURING PURPOSES.

KEY DIAG. No.

EXT. DIAG. No.	
SEL. DIAG. N.	

REL. DIAG. No.
PANEL LAYOUT No.

--	--

© 2004 Blackwell Publishing Ltd, *Journal of Internal Medicine* 255: 105–112

TERMINAL							13	✓
----------	--	--	--	--	--	--	----	---

[illegible]

UE	1	2	3	4	5	6	7	8	9	10	11
----	---	---	---	---	---	---	---	---	---	----	----

100

DTY361112

DTA3010/2.

Background

DTX361U/2:
